

Product Discontinuation Notification

PDN10-10 – CCM

Document revision

Revision	Date	Description	Author
A	November 16, 2010	Creation	R. GIE

Summary

1. Purpose.....	4
2. Discontinuation details.....	4
2.1 Part numbers affected and possible replacement	4
2.2 Reason for discontinuation.....	4
3. Date of application	4

1. Purpose

Discontinuation of CCM04 MK3 connectors with card detect switch including versions with or without hook.

2. Discontinuation details

2.1 Part numbers affected and possible replacement

• Y1143-4248A LFT	CCM04-4248LFT R102	no replacement
• Y1143-4251A LFT	CCM04-4251LFT R102	no replacement
• Y1143-4333B LFT	CCM04-4333LFT R901A	no replacement
• Y1143-5202B LFT	CCM04-5202LFT R901A	no replacement

2.2 Reason for discontinuation

Product is stopped due to low volume and related difficulties of supply for the components

3. Date of application

- Last Time Buy: December 23rd, 2010
- Date of Discontinuation: March 31st, 2010