



DRAWING FOR REFERENCE: This is subject to change without notice
05/31/2013



[PRECAUTIONS FOR HANDLING]

- ◆ Connector insertion and extraction
 - a. Connector shall be extracted vertically by specialised extraction JIG. (Part No. : H. FL-LP-NCCL Code:CL331-0551-7) Never hold the cable when extracting the cable because it damages the connector.
 - b. Insert the connector as perpendicularly to the mating surface as possible by aligning the mating axes of both connectors. Do not excessively slant the connectors when inserting.

RoHS COMPLIANT

| 2 | H. FL75-CONTACT | CL331-0550-4-00 | | | | | |
|---------------------------|--------------------|------------------------|------------|--------------------------|-----------------------|---------|------|
| 1 | H. FL75-LP-084(01) | CL331-0541-3-01 | 3 | CO-6FPFA-SB-CX75 1X0.16 | Hitachi Cable, Ltd. | | |
| NO. | PART NO. | CODE NO. | NO. | PART NO. | MANUFACTURER | | |
| UNITS mm | | SCALE FREE | COUNT | DESCRIPTION OF REVISIONS | DESIGNED | CHECKED | DATE |
| HIROSE ELECTRIC CO., LTD. | | APPROVED : TS. NOBE | 12. 09. 05 | DRAWING NO. | EDC4-133537-18 | | |
| | | CHECKED : NK. NINOMIYA | 12. 09. 05 | PART NO. | H. FL75-LP-084H-A-300 | | |
| | | DESIGNED : YI. FUNADA | 12. 08. 31 | CODE NO. | CL321-2150-0-18 | | |
| | | DRAWN : YI. FUNADA | 12. 08. 31 | | 1/1 | | |