

Product Discontinuation Notification

PCN10-31 March RBP12 Series

Document revision

Revision	Date	Description	Author
A	31 March 2010	Creation	Vincent Acampora

1. Purpose

End of production for the complete RBP12 series

2. Discontinuation Details:

2.1 Part numbers affected:

Item Number

Y46A11007FP_RBP12 108B08 N F S
Y46A11125FP_RBP12 206B06 N F G
Y46A11182FP_RBP12 403B03 N F S
Y46A21182FP_RBP12 403B03 N S S
Y46A11011FP_RBP12 112B12 N F S
Y46AP0088FP_RBP12 202B02 N AD S
Y46A31182FP_RBP12 403B03 N AD S
Y46A11192FP_RBP12 403B03 N F G
Y46A11163FP_RBP12 304B04 N F G
Y46A11004FP_RBP12 105B05 N F S
Y46A11004FP_RBP12 105B05 N F S
Y46A11007FP_RBP12 108B08 N F S
Y46A31011FP_RBP12 112B12 N AD S
Y46A11182FP_RBP12 403B03 N F S
Y46A31211FP_RBP12 602B02 N AD S
Y46A10105FP_RBP12 206B06 C F S
Y46A31061FP_RBP12 112B12 N AD G
Y46A30007FP_RBP12 108B08 C AD S
Y46AP0279FP_RBP12 206S N F G
Y46A11011FP_RBP12 112B12 N F S
Y46A11143FP_RBP12 304B04 N F S
Y46A11012FP_RBP12 112S N F S
Y46A21012FP_RBP12 112S N S S
Y46A31012FP_RBP12 112S N AD S
Y46AP0055FP_RBP12 206S N AD S
Y46A11011FP_RBP12 112B12 N F S
Y46A41163FP_RBP12 403B03 N M G
Y46A11125FP_RBP12 206B06 N F G
Y46A11103FP_RBP12 204B04 N F S
Y46A10062FP_RBP12 112S C F G
Y46A31211FP_RBP12 602B02 N AD S
Y46A10011FP_RBP12 112B12 C F S
Y46A11105FP_RBP12 206B06 N F S
Y46A31061FP_RBP12 112B12 N AD G
Y46A11012FP_RBP12 112S N F S
Y46A11004FP_RBP12 105B05 N F S
Y46A11192FP_RBP12 403B03 N F G
Y46A11011FP_RBP12 112B12 N F S
Y46A31163FP_RBP12 304B04 N AD G
Y46A11163FP_RBP12 304B04 N F G
Y46A11215FP_RBP12 602B02 N F G

C&K Components

www.ck-components.com

Document subject to change without prior notice

Y46A31012FP_RBP12 112S N AD S
Y46A11003FP_RBP12 104B04 N F S
Y46A31142FP_RBP12 303B03 N AD S
Y46A11105FP_RBP12 206B06 N F S
Y46A11192FP_RBP12 403B03 N F G
Y46A11062FP_RBP12 112S N F G
Y46A11211FP_RBP12 602B02 N F S
Y46A11182FP_RBP12 403B03 N F S
Y46A11103FP_RBP12 204B04 N F S
Y46A11125FP_RBP12 206B06 N F G
Y46A11006FP_RBP12 107B07 N F S
Y46A41011FP_RBP12 112B12 N M S
Y46A10012FP_RBP12 112S C F S
Y46A31211FP_RBP12 602B02 N AD S
Y46A11211FP_RBP12 602B02 N F S
Y46A21182FP_RBP12 403B03 N S S
Y46A31182FP_RBP12 403B03 N AD S
Y46A11182FP_RBP12 403B03 N F S
Y46A31143FP_RBP12 304B04 N AD S
Y46A21143FP_RBP12 304B04 N S S
Y46A11143FP_RBP12 304B04 N F S
Y46A31105FP_RBP12 206B06 N AD S
Y46A11105FP_RBP12 206B06 N F S
Y46AP0079FP_RBP12 206S N F S
Y46A31012FP_RBP12 112S N AD S
Y46A31011FP_RBP12 112B12 N AD S
Y46A11012FP_RBP12 112S N F S
Y46A11011FP_RBP12 112B12 N F S
Y46A11011FP_RBP12 112B12 N F S
Y46A11143FP_RBP12 304B04 N F S
Y46A31061FP_RBP12 112B12 N AD G
Y46A11192FP_RBP12 403B03 N F G
Y46A31215FP_RBP12 602B02 N AD G
Y46A31182FP_RBP12 403B03 N AD S
Y46A31105FP_RBP12 206B06 N AD S
Y46A31007FP_RBP12 108B08 N AD S
Y46A03480FP_RBP12M PL 29721235AG
Y46A11101FP_RBP12 202B02 N F S
Y46A11182FP_RBP12 403B03 N F S
Y46A21182FP_RBP12 403B03 N S S
Y46A30143FP_RBP12 304B04 C AD S
Y46A11143FP_RBP12 304B04 N F S
Y46A31012FP_RBP12 112S N AD S
Y46A31006FP_RBP12 107B07 N AD S
Y46A41007FP_RBP12 108B08 N M S
Y46A10104FP_RBP12 205B05 C F S
Y46A31211FP_RBP12 602B02 N AD S
Y46AP0055FP_RBP12 206S N AD S
Y46A31012FP_RBP12 112S N AD S
Y46A31007FP_RBP12 108B08 N AD S

Y46A31006FP_RBP12 107B07 N AD S
Y46A31004FP_RBP12 105B05 N AD S
Y46A30007FP_RBP12 108B08 C AD S
Y46A21050FP_RBP12 107B07 N S S
Y46A21004FP_RBP12 105B05 N S S
Y46A21002FP_RBP12 103B03 N S S
Y46A31061FP_RBP12 112B12 N AD G
Y46A41143FP_RBP12 304B04 N M S
Y46A41012FP_RBP12 112S N M S
Y46A11182FP_RBP12 403B03 N F S
Y46A31006FP_RBP12 107B07 N AD S
Y46A40011FP_RBP12 112B12 C M S
Y46A11004FP_RBP12 105B05 N F S
Y46A11012FP_RBP12 112S N F S
Y460320100P_
Y46A11004FP_RBP12 105B05 N F S
Y46A11004FP_RBP12 105B05 N F S
Y46A11125FP_RBP12 206B06 N F G
Y46A11011FP_RBP12 112B12 N F S
Y46A11011FP_RBP12 112B12 N F S
Y46A11011FP_RBP12 112B12 N F S
Y46A11011FP_RBP12 112B12 N F S
Y46A02620FP_RBP12M PL 29721233 AK AU
Y46A11012FP_RBP12 112S N F S
Y46A11012FP_RBP12 112S N F S
Y46A11103FP_RBP12 204B04 N F S
Y46A11103FP_RBP12 204B04 N F S
Y46A11007FP_RBP12 108B08 N F S
Y46A11007FP_RBP12 108B08 N F S
Y46A11007FP_RBP12 108B08 N F S
Y46A11182FP_RBP12 403B03 N F S
Y46A11182FP_RBP12 403B03 N F S
Y46A11182FP_RBP12 403B03 N F S
Y46A11182FP_RBP12 403B03 N F S
Y46A11182FP_RBP12 403B03 N F S
Y46A11182FP_RBP12 403B03 N F S
Y46A11192FP_RBP12 403B03 N F G
Y46A11192FP_RBP12 403B03 N F G
Y46A11192FP_RBP12 403B03 N F G
Y46A31011FP_RBP12 112B12 N AD S
Y46A31011FP_RBP12 112B12 N AD S
Y46AP0079FP_RBP12 206S N F S
Y46A31211FP_RBP12 602B02 N AD S
Y46A31211FP_RBP12 602B02 N AD S
Y46A31211FP_RBP12 602B02 N AD S
Y46A31211FP_RBP12 602B02 N AD S
Y46A31211FP_RBP12 602B02 N AD S
Y46A11163FP_RBP12 304B04 N F G
Y46A11163FP_RBP12 304B04 N F G
Y46A31061FP_RBP12 112B12 N AD G

Y46A31061FP_RBP12 112B12 N AD G
Y46A31182FP_RBP12 403B03 N AD S
Y46A31182FP_RBP12 403B03 N AD S
Y46A11062FP_RBP12 112S N F G
Y460P0023FP_AXE FA A=10,5
Y46A31142FP_RBP12 303B03 N AD S
Y46A11105FP_RBP12 206B06 N F S
Y46A11105FP_RBP12 206B06 N F S
Y46A11105FP_RBP12 206B06 N F S
Y46A31163FP_RBP12 304B04 N AD G
Y46A31105FP_RBP12 206B06 N AD S
Y46A10105FP_RBP12 206B06 C F S
Y46A10105FP_RBP12 206B06 C F S
Y460400100P_BUTEE INDEXABLE RBP12-2
Y46A21143FP_RBP12 304B04 N S S
Y46A10012FP_RBP12 112S C F S
Y46A10012FP_RBP12 112S C F S
Y46A03480FP_RBP12M PL 29721235AG
Y46A10062FP_RBP12 112S C F G
Y46A11143FP_RBP12 304B04 N F S
Y46A11143FP_RBP12 304B04 N F S
Y46811007EP_RBP12 108B N FP S
Y46811007EP_RBP12 108B N FP S
Y46A11211FP_RBP12 602B02 N F S
Y46A31006FP_RBP12 107B07 N AD S
Y46A31006FP_RBP12 107B07 N AD S
Y46A31007FP_RBP12 108B08 N AD S
Y46A41011FP_RBP12 112B12 N M S
Y46A13828FP_RBP12AD PL 311016EV0397 S
Y46A31002FP_RBP12 103B03 N AD S
Y46A30007FP_RBP12 108B08 C AD S
Y46AP0055FP_RBP12 206S N AD S
Y46002220FP_AXE RBP12 PL 381964
Y46AP0088FP_RBP12 202B02 N AD S
Y46A31012FP_RBP12 112S N AD S
Y46A21012FP_RBP12 112S N S S
Y46A21192FP_RBP12 403B03 N S G
Y46A11009FP_RBP12 110B10 N F S
Y46A11002FP_RBP12 103B03 N F S
Y46A05091FP_RBP12 108B08 CFG (PL29721222)
Y46A01163FP_RBP12F PL 29721223CC S



- 2.2 Reason for discontinuation :
Due to age of the tooling and the overall decrease in usage,we will discontinue the manufacturing of our RBP12 series rotary switch

3. Replacement:

No direct replacement is proposed for this series

4. Effective date June 4th 2010

4. Support

Please contact Customer Service or your local sales representative.