SC:0.50 UNCONTROLLED DOCUMENT PART NUMBER REV. LPA-R01199351S PRELIMINARY IN P/N DIR 28,91 [1,138] — 7.37 [0.290] 9.83 [0.387] 3.81 [0.150] (5 brs') R0.63 [R0.025] (2 PLS.) - 10,16 [0,400] 2.72 [0.107] 2.00 [0.079] R10.03 [R0.395] [1,280] 30.26 [1,191] R10.03 [R0.395] [0.955] 32.26 NOTES: 1. MATERIAL: PC CLEAR 2. LUMEX LOGO & CAVITY NUMBER. TEXTURE DIFFUSED. - 14.23 [0.560] - 27.13 [1.068] -3.56 [0.140] UNCONTROLLED DOCUMENT *UNILESS OTHERWISE SPECIFIED TOLERANCES PER DECINAL PRECISION ARE: X=±1 (±0.039), XXX=±0.5 (±0.020), XXX=±0.25 (±0.010), XXXX=±0.127 (±0.005). LEAD SIZE=±0.05 (±0.002), LEAD LENGTH=±0.75 (±0.030). MIN= +DECINAL PRECISION MAX.= +0.00 (±0.000), XXX=±0.127 (±0.000), XXXX=±0.127 (±0.000), XXXX=±0.000, XXX=±0.000, XXX=±0.00 REV. PART NUMBER

LPA-R01199351S

CUSTOM LIGHTPIPE.

CONFIDENTIAL INFORMATION
THE INFORMATION CONTAINED IN THIS DOCUMENT IS THE PROPERTY OF
LUMEX NO. EXCEPT AS SPECIFICALLY AUTHORIZED IN WRITING BY LUMEX
INC., THE HOLDER OF THIS DOCUMENT SHALL KEEP ALL INFORMATION
CONTAINED HEREIN CONFIDENTIAL AND SHALL PROTECT SAME IN WHOLE OR IN PART FROM DISCLOSURE AND DISSEMINATION TO ALL THIRD PARTIES.

 $\begin{array}{c} \underline{\text{Reliablity Note}} \\ \text{Our nany years of experience data accumulation indicate that} \end{array}$ SOLDER HEAT IS A MAJOR CAUSE OF EARLY AND FUTURE FAILURE. PLEASE PAY ATTENTION TO YOUR SOLDERING PROCESS.



290 E. HELEN ROAD PALATINE, IL 60067-6976 PHONE: +1.847.359.2790 US WEB: www.lumex.com

TW WEB: www.lumex.com.tw DRAWN BY: CHECKED BY: APPROVED BY: DATE: 12.22.04

PAGE: 1 OF 1 SCALE: N/A

Mouser Electronics

Authorized Distributor

Click to View Pricing, Inventory, Delivery & Lifecycle Information:

Lumex:

LPA-R01199351S