

## Final Product/Process Change Notification Document #: FPCN21351X

Issue Date: 2 June 2016

Title of Change:	Addition of Stars Microelectronics as an alternate test location for NCV8170 family.		
Proposed first ship date:	09 September 2016 or earlier upon customer approval		
Contact information:	Contact your local ON Semiconductor Sales Office or <alan.garlington@onsemi.com></alan.garlington@onsemi.com>		
Samples:	Contact your local ON Semiconductor Sales Office		
Additional Reliability Data:	Contact your local ON Semiconductor Sales Office or <tomas.vajter@onsemi.com>.</tomas.vajter@onsemi.com>		
Type of notification:	This is a Final Product/Process Change Notification (FPCN) sent to customers. FPCNs are issued 90 days prior to implementation of the change.  ON Semiconductor will consider this change accepted, unless an inquiry is made in writing within 30 days of delivery of this notice. To do so, contact <pcn.support@onsemi.com>.</pcn.support@onsemi.com>		
Change Part Identification:	No change to the device marking. Marking will continue to reflect the assembly site location.		
Change category:	☐ Wafer Fab Change ☐ Assembly Change ☐ Test Change ☐ Other Test Location addition		
Change Sub-Category(s):  Manufacturing Site Change/Addition  Material Change  Shipping/Pa		☐ Datasheet/Product Doc change ☐ Shipping/Packaging/Marking ☐ Other: Test Location Addition	
		External Foundry/Subcon site(s) Stars Microelectronics Thailand	
Description and Purpose:  Stars Microelectronics, located in Thailand, will be used as an alternate test location for the NCV8170 family of parts. The same tester, hardware and test program will be used as in the primary Malaysia test location. This is being done as a test capacity expansion. There is no other change other than location.  After expiration of this PCN, the NCV8170 family of parts may be tested at either the current Malaysia location or the new Stars Thailand location.			

TEM001092 Rev. H Page 1 of 2



## Final Product/Process Change Notification Document #: FPCN21351X

Issue Date: 2 June 2016

List of Affected Standard Parts:		
NCV8170AMX120TCG	NCV8170BMX150TCG	
NCV8170AMX150TCG	NCV8170BMX180TCG	
NCV8170AMX180TCG	NCV8170BMX250TCG	
NCV8170AMX250TCG	NCV8170BMX280TCG	
NCV8170AMX280TCG	NCV8170BMX300TCG	
NCV8170AMX300TCG	NCV8170BMX310TCG	
NCV8170AMX310TCG	NCV8170BMX330TCG	
NCV8170AMX330TCG	NCV8170BMX360TCG	
NCV8170AMX360TCG	NCV8170BXV120T2G	
NCV8170AXV120T2G	NCV8170BXV150T2G	
NCV8170AXV150T2G	NCV8170BXV180T2G	
NCV8170AXV180T2G	NCV8170BXV250T2G	
NCV8170AXV280T2G	NCV8170BXV280T2G	
NCV8170AXV300T2G	NCV8170BXV300T2G	
NCV8170AXV310T2G	NCV8170BXV310T2G	
NCV8170AXV330T2G	NCV8170BXV330T2G	
NCV8170AXV360T2G	NCV8170BXV360T2G	
NCV8170BMX120TCG		

TEM001092 Rev. H Page 2 of 2