



Errata

Applies to IP65 step motors from pilot production build

Part numbers:

HW23-598-099

HW23-598D-099

HW23-601-099

HW23-601D-099

HW23-753-099

HW23-753D-099

HW23-754-099

HW23-754D-099

HW34-506-099

HW34-506D-099


HW34-696-099

HW34-696D-099


1. Some units have cables that are rated 80°C. These motors should be operated such that the case temperature does not exceed 80°C.
2. The wire colors may differ from our standard. See wiring diagrams below and on the back.

Motors with orange, orange/white, red, red/white, black, black/white, yellow, yellow/white.


Eight lead motor connected in PARALLEL to a bipolar drive.



Eight lead motor connected in SERIES to a bipolar drive.




Eight lead motor connected to a unipolar drive.




Motors with white, orange, brown, green, red, yellow, blue, black.


Eight lead motor connected in PARALLEL to a bipolar drive.



Eight lead motor connected in SERIES to a bipolar drive.




Eight lead motor connected to a unipolar drive.




Motors with white, brown, green, yellow, gray, pink, blue, red.


Eight lead motor connected in PARALLEL to a bipolar drive.



Eight lead motor connected in SERIES to a bipolar drive.



Eight lead motor connected to a unipolar drive.



Mouser Electronics

Authorized Distributor

Click to View Pricing, Inventory, Delivery & Lifecycle Information:

Applied Motion:

[HW23-753](#) [HW23-601](#) [HW23-754](#) [HW23-598](#) [HW34-506](#) [HW34-696](#) [HW24-108](#) [HT34-497](#) [HT23-554](#) [HT23-552](#)
[HT34-496](#) [HT23-553](#) [HT34-495](#)