

Type of Notification: Product Discontinuation

ISSUE DATE	LAST BUY DATE	LAST SHIP DATE	NOTIFICATION NO.
4 April 2011	NONE	30 July 2011	PCN-2011-0406-02

This is to advise you that the following products have been discontinued.

Product ID (Description):

Photointerrupters:

- GP1A047RDZLF
- GP1A05AJ000F
- GP1A44E1J00F
- GP1S296HCPSF
- GP1S44S1J00F
- GP1S525XJ00F
- GP1S73PJ000F
- GP1S94J0000F
- GP1S95J0000F
- GP2A201LCSAF
- GP2L24ABJ00F
- GP2L24BCJ00F
- GP2S24ABJ00F

Description of Change:

Sharp is discontinuing the above parts. No last buy opportunity is being offered.

GP2S60 is the suggested alternative only for GP2L24ABJ00F, GP2L24BCJ00F, and GP2S24ABJ00F. It is a functional replacement only.

Effect of Change:

The part numbers given in the table below are obsolete as of this notice. GP2S60 is the suggested alternative for some these parts, and is only a functional replacement.

OBSOLETE PART NUMBER	REPLACEMENT
GP1A047RDZLF	NONE
GP1A05AJ000F	
GP1A44E1J00F	
GP1S296HCPSF	
GP1S44S1J00F	
GP1S525XJ00F	
GP1S73PJ000F	
GP1S94J0000F	
GP1S95J0000F	
GP2A201LCSAF	
GP2L24ABJ00F	
GP2L24BCJ00F	GP2S60
GP2S24ABJ00F	

In case of further questions, please contact your Sharp sales representative.